

**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Monday, August 24, 2020

HEAVY DECAY IN TIMBER  
HOLDING STONE BALLAST  
IN PLACE AT NE; TYPICAL.

A507 52



Monday, August 24, 2020

HEAVY DECAY IN END OF  
DECK TIMBERS SOUTH  
SIDE; TYPICAL.

A507 53



**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Thursday, August 16, 2018

MAP CRACKING AT  
SOUTHWEST ABUTMENT;  
TYPICAL THROUGHOUT AT  
ABUTMENTS AND WINGS.

A476 63



Thursday, August 16, 2018

MODERATE SPALL AT  
NORTHEAST WING;  
TYPICAL IN FEW AREAS.

A476 64



**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Monday, August 15, 2016

RAIL BOWED OUT  
TOWARDS THE ROADWAY;  
TYPICAL.



A429 71

Monday, August 15, 2016

MODERATE TO HEAVY  
DECAY IN THE TIMBER RAIL  
POST RETAINERS IN MANY  
AREAS.



A429 72

**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Tuesday, August 19, 2014

LIGHT IMPACT DAMAGE TO  
BOTTOM FLANGE OF  
NORTH GIRDER (ACCIDENT  
DAMAGE).

A383 40



Tuesday, August 19, 2014

LIGHT IMPACT DAMAGE TO  
BOTTOM FLANGE OF  
NORTH GIRDER (ACCIDENT  
DAMAGE).

A383 41



Tuesday, August 19, 2014

FEW GOUGES AND  
SCRAPES IN CONCRETE AT  
NORTHWEST ABUTMENT  
AND WEST WING  
(ACCIDENT DAMAGE).

A383 42



**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Tuesday, August 19, 2014

FEW GOUGES AND  
SCRAPES ALONG FACE OF  
WEST ABUTMENT  
(ACCIDENT DAMAGE).

A383 43



Tuesday, August 19, 2014

SCRAPES AND GOUGES IN  
SOUTHBOUND LANE  
ASPHALT (ACCIDENT  
DAMAGE).

A383 44



Tuesday, August 19, 2014

SOUTHWEST OBJECT  
MARKER MISSING.

A383 45



**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Thursday, July 18, 2013

WEST APPROACH.



A359 48

**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Friday, July 29, 2011

LARGE VERTICAL CRACK IN  
CENTER OF EAST  
ABUTMENT.

A307 42



Friday, July 29, 2011

MODERATE SPALLING AT  
JOINT IN NE WING.

A307 43



Friday, July 29, 2011

LIGHT CRACKING WITH  
EFFLORESCENCE ON FACE  
OF SE WING. SPALLED AT  
TOP OF SE WING.

A307 44



**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Friday, July 29, 2011

VERTICAL CRACK IN  
CENTER OF WEST  
ABUTMENT.



A307 45

Friday, July 29, 2011

MODERATE SPALLING AT  
JOINT IN SW WING.



A307 46

**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Thursday, July 30, 2009

TIMBER RAIL AND BALLAST  
RETAINER TIMBERS TIPPED  
AND BOWED OUT ON  
NORTH SIDE. DECAY  
EVIDENT IN RETAINER  
TIMBERS.

A255 08



Thursday, July 30, 2009

TIMBER BALLAST  
CONTAINMENT TIMBERS  
SPLIT, DECAYED AND  
TIPPED OUTWARD ST  
SOUTH SIDE. STONE  
BALLAST PUSHED UP  
ALONG PLANK RAIL AND  
RAIL BOWED OUT.

A255 09



Thursday, July 30, 2009

TYPICAL HEAVY DECAY AT  
ENDS OF DECK TIMBERS  
ON SOUTH SIDE, STONE  
BALLAST CONTAINMENT  
TIMBERS TIPPED  
OUTWARD. VEGETATION  
GROWING.

A255 10



**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Thursday, July 30, 2009

LARGE CRACK IN EAST  
ABUTMENT, CRACKS,  
EFFLORESCENCE AND  
MODERATE SPALLS IN SE  
WING.

A255 11



**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Friday, July 25, 2003

OVERHEIGHT DAMAGE TO  
BOTTOM NORTH SIDE  
FLANGE. LARGE CRACK IN  
EAST ABUTMENT, TYPICAL  
IN WEST.

A158 09



**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Friday, May 18, 2001

OVERHEIGHT DAMAGE TO  
BOTTOM FLANGE AT  
NORTH. PLATES BENT AND  
GOUGED.

A114 25



**HAVERHILL 215/151**  
NHRR(ABD) over US302,NH 10

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Thursday, June 17, 1999

SOUTH ELEVATION.



A037 29